


台風18号通過後の宮崎海岸の様子

平成21年10月8日12時頃撮影



撮影時の波浪・潮位
有義波高:1.63m
有義波周期:11.8秒
実測潮位:T.P.+0.47m


※宮崎港沖の波浪データは細島の波浪観測データから換算を行って求めている

国土交通省・宮崎県
平成21年10月22日

1. 一ツ瀬川河口



撮影日H21.10.8 12:00頃



2.一ツ瀬川河口右岸




撮影日H21.10.8 12:00頃



3.クリーンパーク北




撮影日H21.10.8 12:00頃




4.クリーンパーク前




撮影日H21.10.8 12:00頃



5.KDDIタワー前




撮影日H21.10.8 12:00頃



6.KDDIタワー南




撮影日H21.10.8 12:00頃



7.石崎川河口左岸




撮影日H21.10.8 12:00頃



8.石崎浜養浜箇所




撮影日H21.10.8 12:00頃




9.石崎浜荘北




撮影日H21.10.8 12:00頃



10.石崎浜荘前




撮影日H21.10.8 12:00頃



11.石崎浜護岸(1)




撮影日H21.10.8 12:00頃



12.石崎浜護岸(2)




撮影日H21.10.8 12:00頃




13.石崎浜護岸南



撮影日H21.10.8 12:00頃



14.住吉IC前




撮影日H21.10.8 12:00頃



15.動物園裏BOX北




撮影日H21.10.8 12:00頃



16.動物園裏BOX南



撮影日H21.10.8 12:00頃



17.動物園裏養浜箇所北




撮影日H21.10.8 12:00頃



18.動物園裏養浜箇所



撮影日H21.10.8 12:00頃



19.動物園裏養浜箇所南



撮影日H21.10.8 12:00頃




20. 一ツ葉PA北



撮影日H21.10.8 12:00頃



21. 一ツ葉PA前



撮影日H21.10.8 12:00頃



22.シーガイアIC前




撮影日H21.10.8 12:00頃




23.サンビーチーツ葉



撮影日H21.10.8 12:00頃



24.大淀川河口



撮影日H21.10.8 12:00頃

